

Installation Position

1. The product should be as close to the protected parts as possible. For example, in the motor, the product should be embedded in the upper end of the motor stator coil. If the test conditions are met, the temperature field of the motor should be measured to determine the highest temperature point.
2. During the installation of the product, it is forbidden to strike by gravity, and the product shall not be extruded at the installation position, so as to avoid deformation of the product shell, which will seriously affect the protection performance of the product.

Warnings

Risk of Material Damage and Hot Enclosure

1. The product's side panels may be hot, allow the product to cool before touching.
2. Follow proper mounting instructions including force values. Failure to follow these instructions can result in serious injury, or equipment damage. Hazard of Electric Shock, Explosion or Arch Flash.
3. Verify all connections and replace all covers before turning on power. Failure to follow these instructions will result in death or serious injury.
4. Disconnect all power before installing or working with this equipment.